




- ## NOTES

1. DO NOT CONNECT OPERATING PLATFORM DIRECTLY TO GROUND MAT.
2. DO NOT CONNECT EQUIPMENT PLATFORM DIRECTLY TO GROUND MAT.
3. USE 4/0 AWG STRANDED COPPER CABLE TO BOND THE TWO PLATFORMS TOGETHER.

REFERENCE DRAWING

SWITCH OPERATING PLATFORMS -
STEEL DESIGN AND DETAILS_____31 2014



SUPERSEDES DWG NO. 40-D-4874

UNITED STATES DEPARTMENT OF ENERGY
WESTERN AREA POWER ADMINISTRATION
CORPORATE SERVICES OFFICE - LAKEWOOD, COLORADO

SUBSTATION STANDARDS
SWITCH OPERATING AND
EQUIPMENT PLATFORMS
ELECTRICAL DESIGN AND DETAILS

DESIGNED W.L. SOPER _____ APPROVED DON WARNER _____
FOR DIRECTOR, DIVISION OF
SUBSTATION DESIGN

C _A F	MAY 18, 1979	31	1075
------------------	--------------	----	------